

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

# **Erratic Transducer Display**

# **Models Affected**

NOTE: Identify the model number first and then reference the serial number range.

Models Covered	Serial Number
W55L Wireless/48" shaft 970100090	9B928788–9B928788
	9B929117–9B929128
	9B930098–9B930103
	9B930346–9B930375
	9B931874–9B932657
	9B932664–9B933601
	9B933603–9B933623
	9B933625–9B933625
	9B933751–9B933754
	9B933938–9B933976
	9B947069–9B950073
	9B928791–9B928791
	9B929129–9B929143
W55L Wireless/54" shaft 970100100	9B930376–9B930386
	9B931850–9B931873
	9B932616–9B932646
	9B933421–9B933421
	9B933469–9B933508
	9B933977–9B933991
	9B933993–9B934001
	9B934918–9B934989
	9B936242–9B936242
	9B937031–9B937048
	9B947416–9B950055

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

Models Covered	Serial Number
W75L Wireless/48" shaft 970100110	9B928789-9B928789
	9B929144–9B929155
	9B930387-9B930422
	9B931032-9B931032
	9B931898–9B931920
	9B932677–9B932688
	9B933370–9B933417
	9B933721–9B933721
	9B933724–9B933735
	9B934002–9B934025
	9B934990–9B935049
	9B936382–9B936405
	9B937237–9B937320
	9B939160-9B939207
	9B940194–9B940255
	9B947368–9B950031
	9B928790–9B928790
	9B929156-9B929171
	9B930423-9B930443
	9B931921–9B931944
	9B932689–9B932712
	9B933418–9B933418
	9B933420–9B933420
	9B933422–9B933422
W75L Wireless/60" shaft 970100120	9B933424–9B933428
970100120	9B933430–9B933468
	9B933736–9B933750
	9B934026–9B937826
	9B938788–9B939159
	9B940167–9B940167
	9B940716–9B940724
	9B940734–9B940764
	9B946577–9B953029

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

#### Situation

Exposure to temperature changes causes delamination of the potted sonar transducer crystal from the polycarbonate nose cone material allowing an air gap to form. The Lowrance® transducer bottom signal is erratic or does not display.



## Correction

Test the sonar display with a working transducer to ensure that the sonar display is operative. If the sonar display functions properly using a working transducer, replace the nose cone and O-ring on all serial numbers listed. Refer to **Models Affected**.

For lower unit assembly and disassembly instructions, refer to the **MotorGuide Wireless Service Manual**.

#### Parts Required

Part	Part Number
Wireless nose cone	M899787T1
Red teflon-coated O-ring	MBV21701T

## Warranty

MotorGuide will credit the dealer for the costs of parts and labor. Complete the warranty claim by providing:

- · Model and serial number of the trolling motor
- Proof of purchase of the Wireless trolling motor
- Quantity: One nose cone and one O-ring as required
- 1.0 hour labor
- Warranty Flat Rate Code: SB10
- Part Code: 831
- Failure Code: 07

#### **US AND CANADA**

Complete and process the claim via MercNET or return a warranty claim form. Mail to: Mercury Marine P.O. Box 1939 Fond du Lac, WI 54936 Fax +1 920 929 5893

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

#### INTERNATIONAL

Follow instructions issued by the Marine Power International office or by an authorized Marine Power Distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.