



service bulletin

- WARRANTY INFORMATION SERVICE INFORMATION
 PARTS INFORMATION

Bulletin No. 2002-03

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Expired Fix Campaigns

Models Affected

Mercury/Mariner/Force

The following field fix campaigns have expired. Warranty credit will no longer be issued for these campaigns. Most new bulletins will limit warranty credit to one year from the date the bulletin is issued, unless otherwise specified. Check the issue date of new bulletins, located at the lower left corner of the front page.

SERVICE BULLETIN NO.	PRODUCT LINE	BULLETIN DESCRIPTION
91-20	Mercury/Mariner	Flywheel Replacement - 1991 40 (4 Cylinder)
91-28	Mercury/Mariner	Power Trim Relay Inspection - 1992 50 and 60
91-33	Mercury/Mariner	Piston Pin Thrust Washer Replacement - 1992 75 thru 200 HP
92-16	Mercury/Mariner	Timing Decal - 1991 and 1992 200 HP Carburetor Models
93-5	Mercury/Mariner	Carburetor Main Jet Replacement - 1993 200 Models
93-12	Mercury/Mariner	Detonation Sensor and Module - 1993 200 Magnum EFI/XRI
93-20	Mercury/Mariner	1994 225 Update
93-21	Mercury/Mariner	Fuel Pump Replacement - 40 thru 225
94-11	Mercury/Mariner	Powerhead Water Ingestion - 225 Model
95-7	Mercury/Mariner	Driveshaft Replacement 30/40 and 50 (4-Stroke)
95-15	Mercury/Mariner	Shift Shaft Seal - 225 & 250

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Expired Fix Campaigns (cont.)

SERVICE BULLETIN NO.	PRODUCT LINE	BULLETIN DESCRIPTION
96-1	Mercury/Mariner	Power Trim Relay - 135 thru 200
96-5	Mercury/Mariner	Detonation Control Module Replacement - 200 HP, EFI
96-7	Mercury/Mariner	Fuel Pump Replacement - 45/50 (4-Stroke)
96-11	Mercury/Mariner	Crankshaft Replacement - 45/50 (4-Stroke)
96-12	Mercury/Mariner	Camshaft Oil Seal Replacement - 45/50 (4-Stroke)
97-18	Force Outboard	Propeller Shaft Seal - 40, 50, and 75 HP
98-16	Mercury/Mariner, and Force Outboard	Hose Replacement
2000-15	Sport Jet	Voltage Regulator - 240 HP Jet Drive

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided to be used for solely and exclusively by the original recipient and as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.