

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Worm Type Hose Clamp Ends and Edges - Laceration Warning

Models Affected

Models Covered
Mercury SDI, TDI, and QSD Diesel Engines


Situation

Some of the models above may have unprotected sharp ends on worm type hose clamps. These exposed sharp ends can cause a laceration if they come in contact with a part of the body during servicing, inspection, or maintenance of the power package.

Correction

To limit the risk of laceration when working on these models, take care to observe where body parts are being placed when working around the power package. Also, be sure that you have proper footing and a stable area to stand or sit when you are working around the power package.

If uncovered hose clamp ends are found, install the appropriate hose clamp end cover part number listed below.



Parts Required

Qty.	Description	Part Number
1	Cover, hose clamp end (1/2")	8M6500037
1	Cover, hose clamp end (1/4-5/16")	8M0074363

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Warranty

Mercury Marine will credit the dealer for the cost of parts and labor while the engine is under regular warranty.

Complete warranty claim listing:

- Labor: 0.4 hour
- Warranty flat rate code: SB04
- Qty. of cover, hose clamp end—P/N 8M6500037 or 8M0074363
- Part code: 924
- Fail code: 00

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.