

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Diagnostic Manual Oil Pump Output Test

Models Affected

- 250XS OptiMax DFI
- 300XS OptiMax DFI

Situation

This Bulletin is issued to correct a mistake in **Section 2A - Oil Injection System Theory, Oil Pump Output**, in the Diagnostic Manual.

Corrective Action

Please place the supplied label over the entire **Oil Pump Output** procedure of the manual.

- Page 2A-20, 250XS OptiMax DFI Diagnostic Manual (90-8M8000016)
- Page 2A-19, 300XS OptiMax DFI Diagnostic Manual (90-8M8020380)

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.