

WARRANTY INFORMATION

SERVICE INFORMATION

Bulletin No. 2002-17

PARTS INFORMATION

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Pinion Nut

Models Affected

All Push-Pull Steering Systems with High Thrust (60-109 lbs.).

Situation

If the Pinion Nut breaks on High Thrust trolling motors, it should be replaced with the part of the most recent design.

Parts Required

Qty: 1 MAF39804 Pinion Nut

Dealer Parts Inventory

Use parts of the previous design that are in dealer inventory on low thrust models (54 lbs. and below).

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.