

WARRANTY INFORMATION

SERVICE INFORMATION

Bulletin No. 2002-21

PARTS INFORMATION

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Foot Pedal Pulley Screws

Models Affected

All Tour and Tour Edition models manufactured prior to November 20, 2002

Situation

Pulley screws on the Tour Edition and Tour foot pedal have been backing out.

Correction

Apply one drop of Loctite 222 to the threads of the pulley screws. Undamaged screws may be reused.

Parts Required

92-809818 Loctite Threadlocker 222

Qty. 2 10-MFM13304 Pulley screws

Warranty

MotorGuide will credit the dealer for the cost of parts and labor through December 2005.

Submit a warranty claim through your normal warranty processing channel, listing:

Model/Serial number

Qty. 2 10-MFM13304 Pulley Screw (if required)

Flat Rate Code: SB03 0.3 hour

Part Code: 802

Failure Code: 00

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.