

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Tour Edition Motors with 63" Cables

Models Affected

Models Covered
Tour Edition Series with 45 inch or shorter columns and 63 inch foot-pedal steering cables

Serial Numbers Affected

9BX43GAAF		
9B626894 - 9B626917	9B815194 - 9B815195	9B815976
9B627054 - 9B627119	9B815197 - 9B815211	9B816027 - 9B816033
9B627709 - 9B627735	9B815283	9B816079 - 9B816088
9B627801 - 9B627882	9B815314 - 9B815318	9B816362 - 9B816374
9B628691 - 9B628717	9B815335 - 9B815343	9B816438 - 9B816440
9B628772	9B815356 - 9B815359	9B816540 - 9B816560
9B628793 - 9B628840	9B815377 - 9B815392	9B816628 - 9B816668
9B629298 - 9B629333	9B815407 - 9B815410	9B816830 - 9B816832
9B630442 - 9B630465	9B815432 - 9B815436	9B816837 - 9B816856
9B815063 - 9B815064	9B815444 - 9B815461	9B816874 - 9B816904
9B815080 - 9B815190	9B815626 - 9B815633	

9BT42GCAF		
9B628293 - 9B628312	9B815275 - 9B815313	9B816471
9B628315	9B815320 - 9B815326	9B816600 - 9B816623
9B815072 - 9B815073	9B815344 - 9B815365	9B816650 - 9B816661
9B815081 - 9B815114	9B815437 - 9B815443	9B816669 - 9B816680
9B815116	9B815921 - 9B815975	9B816773 - 9B816785
9B815127 - 9B815237	9B816089 - 9B816150	9B816787 - 9B816790
9B815246	9B816280 - 9B816417	9B816803 - 9B816809
9B815256 - 9B815259	9B816431 - 9B816434	9B816833 - 9B816836
9B815270 - 9B815273	9B816441 - 9B816442	9B817108 - 9B817123

9BC31EAAJ		
9B627583 - 9B627605	9B628423	9B816767 - 9B816772

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Tour Edition Motors with 63" Cables

9BC31EAAJ		
9B628011 - 9B628321	9B628753 - 9B628779	9B816857 - 9B816862
9B628323 - 9B628327	9B628973 - 9B628981	9B816916 - 9B816918
9BT42GAAF		
9B627164 - 9B627582	9B628624 - 9B628936	9B630059 - 9B630125
9B627636 - 9B627708	9B628995 - 9B629012	9B630535 - 9B630556
9B627904 - 9B628404	9B629356 - 9B629403	9B816948 - 9B817086
9B628620		
9BX43ZCAM		
9B815212 - 9B815213	9B815366 - 9B815376	9B816034 - 9B816038
9B815333 - 9B815334	9B815403 - 9B815406	9B817087 - 9B817089
930010014		
9B628417 - 9B628519	9B629087 - 9B629091	
9B629037 - 9B629056	9B629263 - 9B629285	
930010020		
9B626823 - 9B626839	9B629416 - 9B629469	9B816562 - 9B816576
9B628135 - 9B628292	9B630015 - 9B630058	9B816587 - 9B816599
9B628859 - 9B628882		
930010040		
9B627963 - 9B628752	9B629092	9B815144 - 9B815193
9B628771	9B629286 - 9B629291	9B815196
9B629057 - 9B629086	9B815140	9B816905 - 9B816915
9BX43ZAAS		
9B301897 - 9B301902	9B629334 - 9B629346	
9B627778 - 9B627800	9B815319	
9BX43ZAAM		
9B628685 - 9B628690	9B816749 - 9B816754	
9BT42ZAAM		
9B301891 - 9B301896	9B628558 - 9B628569	9B816634 - 9B816649
9B627487 - 9B627492	9B628883 - 9B628994	9B816755 - 9B816760
9B628053 - 9B628064	9B816529 - 9B816534	9B816940 - 9B816947
9BT42ZAAS		
9B627475 - 9B627486	9B628065 - 9B628076	9B628982 - 9B628988
9B627766 - 9B627777	9B628570 - 9B628575	9B629292 - 9B629297
9BU42FACT		
9B626924 - 9B627474	9B628017 - 9B628052	9B816577 - 9B816873

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

9BU42FACT		
9B627606 - 9B627635	9B630417 - 9B630441	9B816919 - 9B816932
9BT42ZCAM		
9B815917 - 9B815920	9B816293 - 9B816295	9B816388 - 9B816393


Situation

The trolling motors referenced above are impacted by a foot-pedal cable that has the potential for the outer cable shell to collapse causing a soft steering pedal condition.

This situation will apply to the models referenced above with 45 inch or shorter columns and 63 inch foot-pedal steering cables. Replace the cables on these models regardless of any other service issue.

Correction

Replace the two cables that connect the foot-pedal to the motor and control the steering. After the cable issue was identified, part numbers for the improved replacement cables were changed. Additionally, the improved replacement cables have been denoted by the factory with a blue mark which is located near the cable adjustment springs on the base of the foot-pedal (see photo for the blue mark location). If you are servicing one of these Tour Edition models that do not have blue markings on the foot-pedal cables, replace the cables.



16861

a - Blue marks located on cables beneath adjustment springs

Parts Required

Qty.	Description	Part Number
1	Cable Assembly - Short	MPM02753
1	Cable Assembly - Long	MPM02754

Dealer Inventory

If you have any of the below listed parts in your inventory, return them to Mercury Marine. Follow the normal warranty parts return procedure. Please reference service bulletin 2005-05 on the claim form.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Description	Part Number
Foot-pedal assembly	MXC30034T
Foot-pedal assembly	MXC30035T
Cable assembly control	MAP327482
Cable assembly control	MAP327492
Cable assembly - short	MPM02743
Cable assembly - long	MPM02744

Warranty

Repairs will be covered until June 30, 2008.

Complete warranty claim providing:

- Model and serial number of the trolling motor
- Proof of purchase and/or copy of customer letter
- 1.0 hour labor
- Warranty Flat Rate Code: SB10
- Part Code: 805
- Failure Code: 05

U.S. AND CANADA

Complete/process claim via MercNET or a warranty claim form. Mail to:

Mercury Marine
P.O. Box 1939
Fond du Lac, WI 54936
Fax 1-920-929-5893

INTERNATIONAL

Follow the instructions issued by the Marine Power International Office or by your distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.