

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## Corrections To HP575 SCi Service Manual #8

### Models Affected

HP575 SCi

### Situation

Information about the spark plug firing order and fuel pressure was stated incorrectly in Service Manual #8, part number 90-840542.

### Corrections

The following corrections were made:

Page 3A-3; corrected firing order: 1-8-4-3-6-5-7-2

Page 5A-2; corrected fuel pressure at idle: 193 kPa (28 psi), fuel pressure at WOT: 179 kPa (26 psi)

The corrected Service Manual is available electronically on MercNET. A revised manual will not be printed and distributed.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.