

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

9.9 HP FourStroke Command Thrust Driveshaft Holding Tool

Models Affected

Models Covered	Serial Number Or Year
9.9 HP FourStroke BigFoot and Command Thrust	All

Scope

Worldwide

Situation

Mercury Marine has found an error in the service manual for the 9.9 HP FourStroke Command Thrust engine, part number 892248R01. The gearcase special tools section has the incorrect part number published for the driveshaft holding tool.

Reference the chart below for the appropriate driveshaft holding tool part number.

Engine Model	Published Driveshaft Holding Tool Part Number	Correct Driveshaft Holding Tool Part Number
Mercury 9.9 HP Command Thrust	91-804762 (incorrect)	8M0045588

NOTE: Do not discard part number 91-804762, as this special tool is the driveshaft holding tool for the 15/20 HP FourStroke engine family.

Correction

Order the appropriate driveshaft holding tool for the 9.9 HP FourStroke Command Thrust engine. Also, please place a copy of this service bulletin in the above mentioned service manual for future reference.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.