

TO: SERVICE MANAGER  MECHANICS   
PARTS MANAGER

**No. 93-6**

## **A. ADD WATER INLET HOSE CLAMP**

### **Model**

MCM 5.0L, 5.0LX, 5.7L Alpha Stern Drive Engines Only  
Serial Number: All

*NOTE: This does not effect any Alpha engines with a remote oil filter.*

### **Inspection**

When you change the oil filter on these model engines, look for signs of wear on the filter in the area where the seawater inlet hose (from the transom plate) runs next to the filter.

### **Correction**

If the seawater hose has worn the paint off the old filter or the hose is touching the new filter after its installed, please install the special clamp to hold the hose away from the filter. Secure the special clamp to the flywheel housing at housing mounting bolt that is the closest to the filter. Remove the flat washer from this bolt before installing the clamp and housing bolt.

### **Parts Required**

(1) 54-64489 Special Clamp