

TO: SERVICE MANAGER  TECHNICIANS   
PARTS MANAGER

**No. 94-13**

▲ = Revised 6/30/94

## **This Bulletin Supersedes the Recommended Usage of 2-4-C in all of the Current Service Manuals and all Operation & Maintenance Manuals**

### **A. Universal-Joint & Gimbal Bearing Grease**

#### **Models**

▲ All Alpha & Bravo Drive Units with greaseable U-Joint Cross & Bearings plus all Transom Gimbal Bearings

#### **Problem**

The present 2-4-C grease that is listed in the service manuals the Operation and Owners Manuals and the Accessories Manual has had (Teflon) added and at this time is not recommended for use in the Greaseable U-Joint Cross & Bearing or in the Gimbal Bearing on any Alpha or Bravo Drive Unit, that has a greaseable Cross & Bearing assembly in it.

#### **Correction**

The following grease will supersede the use of the 2-4-C for the U-Joint and Gimbal bearing application in MerCruiser stern drives with the Greaseable Cross & Bearing also in all Gimbal Bearing usage.

▲ The new name of the grease is (**Universal-Joint & Gimbal Bearing Grease**)  
The new part numbers are as follows:

828052A3 for three (3.5 oz.) Cartridges  
828052A4 for three (14 oz.) Cartridges

▲ The 2-4-C may be used in all other areas because the (Teflon) that is in the 2-4-C will not have any adverse effects in those areas, This grease should be available in Quicksilver stock by August 1 1994.