


**Brush Card/Mosfet Screw Length** 

## **Models Affected**

2000 & 2001 Model Year Excel- EX54SP, EX71SP, EX82SP, EX109SP Energy- EF54P, EF67P Tour Edition- TE782VP, TE109VP Competition Series- 767P

## Situation

Should you encounter a situation in which a motor runs well out of water but has no power when submerged, inspect the Mosfet screw that holds the Mosfet assembly to the commutator cap to see if the screw is contacting the brush card. If a white, powdery substance is evident electrolysis has occurred.



a - Original Mosfet Screw 7/8 in. (22 mm)

**b** - Replacement Mosfet Screw 3/4 in. (19 mm)

# Correction

If electrolysis has occurred replace the brush card and the Mosfet screws. The replacement screws are 1/8 in. (3 mm) shorter than the original screws.

THE INFORMATION IN THIS DOCUMENT IS <u>CONFIDENTIAL AND PROTECTED BY COPYRIGHT</u> AND IS THE PROPERTY OF MOTORGUIDE. This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

## **Parts Required**

Qty. 2 MR22902 Mosfet screw

Qty. 1 Brush Card-refer to appropriate Parts List for correct part (dependant on model)

#### Warranty

MotorGuide will credit the dealer for the cost of parts and labor for one year from the issuance of this advisory. Please note the month and year located at the lower corner of the front page of this advisory.

Complete warranty claims listing:

- Model/Serial number
- Qty. 2 MR22902 Mosfet screw
- Qty. 1 Refer to appropriate Parts List for correct brush card (dependant on model)
- Eight tenths (0.8) hour labor
- Flat Rate Code: ET20

USA and Canada: Complete warranty claim form (use Midas/MercNet if available).

**INTERNATIONAL:** Follow instructions issued by Marine Power International office or by your distributor.

Fax to:1-920-929-5893Mail to:Mercury Marine<br/>Attn.: Warranty Department

P.O. Box 1939

Fond du Lac, WI 54936-9983

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.