

Warranty Information Service Information

Sterndrive No. 2003-05

 Parts Information

OEM No. 2003-02

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

Availability of Splash Plate Kit

Models Affected

Bravo Sport Master Drives with Splash Plates retained with one countersunk, flat head machine screw.

Situation

In certain applications, splash plates retained with one countersunk, flat head machine screw could loosen and separate from drive units. A kit is now available that replaces the existing splash plate with a new plate and additional fasteners.

Correction

To replace existing splash plates with new plates and additional fasteners, order the kit 842825T01.

Warranty

Submit a warranty claim through your normal warranty processing channel and list the following:

- The engine serial number
- Qty: 1 P/N 842825T01
- 0.5 hour labor
- Warranty labor code: NJC
- Part code: 232
- Failure code: 24

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.