



# Service Bulletin

Bulletin No. 2005-67  
CMD 2005-07

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## 1.7L Parts Change Notice Due To Recreational Craft Directive (RCD)

### Models Affected

Application	Model	Serial Number
CMD	1.7 MS and 1.7 MJ models with power steering	88142000 And Above
CMD	1.7 MS models without power steering	88130150 And Above
CMD	1.7 MI models	88121100 And Above

### Situation

To conform to the RCD certification guidelines, the 1.7 MS, 1.7 MI, and 1.7 MJ fuel injection pump and turbocharger have been changed. The new fuel injection pump and turbocharger will affect the models and serial numbers listed above. All older model engines will continue to use the current fuel injection pump and turbocharger part numbers.

The current removal and installation procedures for the turbocharger and fuel injection pump, including the fuel injection pump timing procedure, will apply to the new RCD parts.

Part Description	Current Part Number	New RCD Part Number
Fuel injection pump	882554	898149
Turbocharger	882562	898148

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.