

TO: PARTS MANAGER
SERVICE MANAGER

No. 93-5

A. REPLACEMENT IGNITION RESISTOR WIRES

Models

L4, L6 and V8 Engines with Point Ignition Systems

Replacement Wire Kits

There are two kits available to repair a damaged resistor wire that is built into the engine wiring harness. All Parts Lists show only one kit. The 4 cylinder engines uses a different kit than the 6 or 8 cylinder engines. Instructions come with each kit.

(1) 84-94227A2 Resistance Wire Kit, 3 ft. Long-All 4 Cylinder Engines.

(1) 84-94227A5 Resistance Wire Kit, 5 ft. Long-All 6 and 8 Cylinder Engines.